



September 7, 2000

Mr. Dale Hatfield Office of Engineering and Technology Federal Communications Commission 445 12th Street, SW, Room 7-A-340 Washington, DC 20554

Re: Final Service Disruption Report

Dear Mr. Hatfield:

Pursuant to the requirements established in the Report and Order in CC Docket No. 91-273 (Amendment of Part 63 of the Commission's Rules to Provide for Notification by Common Carriers of Service Disruptions), PACIFIC BELL submits the attached Final Service Disruption Report associated with a service disruption in Napa County and Saint Helena, California on August 8, 2000.

An Initial Service Disruption Report was faxed to the FCC's Monitoring Watch Officer on that date.

Please stamp and return the provided copy to confirm your receipt. Please contact me if you have questions regarding this service disruption.

Sincerely,

Enclosures

CC: Bob Kimball Kent Nilsson



A member of the SBC global network

Retention Period:	6 Years	FCC :	SERVICE	DISR	UPTION REPORT						
Type of Repo	ort:	☐ Initial Report	: 🗆	Update	⊠ Final						
Occurred:	Date: 08/08	3/2000 Time:	23:39 PDT		50,000 or More Customers 30,000 - 49,999 Customers						
Ended:	Date: 08/09	0/2000 Time:	02:47 PDT		Fire incident ≥ 1,000 lines Special Offices/Facilities						
Duration (in r	minutes):	188 mi	inutes		Special Offices/Facilities ☐ 911 ☐ Major/Medium Airport ☐ NCS Request						
Geographic Area Affected: Napa County and Saint Helena, California											
Estimated Customers Affected: 37,100											
Type(s) of Services Affected: ☐ Local (Intraoffice) ☐ IntraLATA ☐ InterLATA ☐ 800 ☐ LIDB ☐ Operator Services ☐ Interexchange ☐ Switched Access (interoffice) ☐ Cellular ☐ International ☐ FAA ☐ All											
Estimated Blocked Calls: 6											
Apparent or Known Cause of the Outage: At 23:39 PDT, on Tuesday, August 8, 2000 at NEC 560 fiber optic multiplexer in the Vallejo, California central office did not switch three of eleven T-3 carrier systems to protect channels after a SWI 48 circuit card failure. This is a single thread route with no physical diversity. The three systems carried six E911 trunks to the Napa County Sheriff and two E911 trunks to the Saint Helena Police Department Public Safety Answering Points (PSAP's) which were isolated from the E911 tandem due to the outage. The Napa County Sheriff's PSAP serves approximately 32,000 lines and the Saint Helena Police Department PSAP serves approximately 5,100 lines. Contingency plans to route 911 calls to alternate PSAP's could not be implemented due to loss of logging channels to the affected offices.											
		erage of the eve curred during the		ll was not	made aware of any life						
Root Cause is	s Hardware Fa	nilure - Processor	Community F	ailure.							

Name and Type of Equipment Involved: NEC 560 Fiber Optic Multiplexer

Specific Part of Network Involved: E911

Methods used to Restore Service: Replaced defective SWI 48 circuit card in the NEC 560 fiber multiplexer.

Steps Taken to Prevent Recurrence:

- 1. Orders were written to diversify E911 trunks in Vallejo and St. Helena. Orders were completed on Wednesday, August 16, 2000.
- 2. Supplier (NEC) has been contacted for support on Product Change Notice (PCN) 907129 to replace spare and working SWI 48 circuit packs in all NEC 560 Fiber Optic Multiplexers.
- 3. A Transport Technical Support (TTS) Flash was distributed to all transport personnel in Pacific and Nevada Bell notifying them of the problem and the solution.

Applicable Best Practice: Pacific Bell reviewed the Network Reliability: A Report to the Nation, Section F, dated June 1993 and Network Reliability: The Path Forward, Focus Group IV, Essential Communications During Emergencies, dated April 1996 and evaluated all recommendations and best practices. Based on the Root Cause analysis the most appropriate focus area is:

Network Reliability: A Report to the Nation

Reference: 6. Countermeasures and Recommended Best Practices

- The key element in most of the best practices cataloged in this report is diversity. The following is a set of working criteria used to define diversity:
 - A diverse network element (e.g., transport facility) is immediately available and there is nearly instantaneous restoration of services (full or partial).

Network Reliability: A Report to the Nation

Reference: 6.1.1 Diverse Routing of Interoffice Facilities

 When circuits are rearranged, unless special indications within the provisioning system (e.g., TIRKS) are made to keep circuits diverse, chances are high that circuits that were originally designed to be diverse will be collapsed into non-diverse facilities.

Network Reliability: The Path Forward

Reference: 6.1 Best Practice ES01 Diverse Interoffice Transport Facilities

• The ECOMM Team recommends diversification of 9-1-1 circuits over multiple, diverse interoffice facilities.

Best Practices Used: Pacific Bell observes those practices that are consistent with providing outstanding customer service.

Analysis of Effectiveness of Best Practices: The supplier was notified that support is needed to implement the PCN to change out the SWI 48 circuit pack in all NEC 560 Fiber Optic Multiplexers. Circuit rearrangement orders were issued and completed to provide carrier diversity.

Prepared by: Jim Lankford Telephone: 210-886-4589

Date submitted: 09/07/2000 **Time:** 09:40 CDT

128



A member of the SBC global network

Retention Period:	6 Үэвгс		FCC	SERVI	CE DI	SRUI	PTION	REPOR	ξ-			
Type of Report	t:	🛭 Init	lal Repor	t	Upd	ate	☐ Fi	nai				
Occurred:	Date:	08/08/2000	Time:	23:39 PD	T	<u></u> 50,i	000 or Mo	re Custome	ŗs			
Ended:	Date:	08/09/2000	Time:	02:47 PD	τ	Fire	: incident 2	99 Custome 1,000 lines	: [
Duration (in ml			188 mi				911 Major/Med NCS Requ	s/Facilities dium Airport uest	ţ			
Geographic Area Affected: Napa County and Saint Helena, California												
Estimated Customers Affected: 38,000												
Type(s) of Services Affected: Local (Intraoffice) IntraLATA InterLATA 800 LIDB Operator Services Interexchange Switched Access (Interoffice) Cellular International E911/911 FAA AII												
Estimated Blocked Calls: Under Investigation												
Apparent or Known Cause of the Outage: At 23:39 PDT, on Tuesday, August 8, 2000 a NEC 560 fiber optic multiplexer in the Vallejo, California central office did not switch 3 T-3's to protect channels after a SWI 48 circuit card failure. The Napa County Sheriff and Saint Helena Police Department Public Safety Answering Points (PSAP's) were affected by the outage. Contingency plans to route 911 calls to alternate PSAP's could not be implemented the to loss of logging channels to the affected offices.												
There was no media coverage of the event.												
lame and Type of Equipment Involved: NEC 560 Fiber Optic Multiplexer												
specific Part of I	Vetwo	rk involved:	E911									
lethods used to Restore Service: Replaced defective SWI 48 circuit card in the NEC 560.												
repared by: Jim ate submitted:	1 Lank 08/09/	ford /2000		Te	lephone Time	e: 210-8 e: 08:25	886-4589 CDT					